# ENVIRONMENTAL SITE ASSESSMENT FOR THE EVALUATION OF POTENTIALLY HAZARDOUS MATERIALS

Vacant area 2900 Briarwick Ln. Houston, Texas 77093

Prepared for
City of Houston
Building Services Department

P.O. Box 1562 Houston, Texas 77251

Attn.: Mr. Gabriel Mussio

Date of the report: January 06, 2006

Prepared by

RAO ENVIRONMENTAL 19333 Hwy. 59 North, Suite 190 Humble, Texas 77338

Tel: 281-548-7050 Fax: 281-548-7030

# TABLE OF CONTENTS

1.0	EXECUTIVE SU	JMMARY	1				
2.0	OBJECTIVE		3				
	2.1 Scope of wor	·k	3				
	2.2 Client author	rization	3				
	2.3 Limitations a	and assessment	3				
3.0	SITE LOCATIO	N AND DESCRIPTION	4				
4.0	ENVIRONMEN	TAL SETTING	5				
	4.1 Surface water	r characteristics	5				
	4.2 Groundwater	characteristics	5				
5.0	ENVIRONMEN	TAL REGULATORY REVIEW	6				
	5.1 Federal and	State Regulatory Agency Inquiries	6				
	5.2 Local Gover	nment Inquiries	8				
6.0	HISTORICAL U	SAGE INFORMATION	9				
	6.1 Current ownership						
	6.2 Prior owners	ship	9				
	6.3 Historical C	ity Directories and Fire Insurance Maps	9				
	6.4 Review of the	ne aerial photos	10				
7.0	RESULTS OF T	HE ON-SITE INSPECTION	11				
	7.1 Observation	S	11				
	7.2 Hazardous s	ubstance identification/inventory	12				
	7.3 PCBs and R	adon	12				
	7.4 Lead paint c	ontaining materials	12				
	7.5 Sampling re	sults	12				
8.0	FINDINGS ANI	CONCLUSIONS	13				
9.0	REFERENCES		14				
10.0	APPENDICES						
	Appendix-A R	ecord of communications					
		ecorded chain of title					
		acilities found in the area of review					
	Appendix-D A	erial photographs					
		ite photographs					

#### 1.0 EXECUTIVE SUMMARY

This report represents results of an Environmental Site Assessment of a vacant property located on 2900 Briarwick Ln., Houston, Texas 77093. The subject site was inspected on December 29, 2005 by Mr. Zahir Jamal of RAO ENVIRONMENTAL. The subject property is a vacant land and is 7,650 square feet in area. The property is a vacant land with grassy areas. Hazardous materials were not found at the site. Review of the title search does not indicate property owners, whose names might indicate possible environmental concerns about the site.

Review of the regulatory lists indicates that the subject property is not listed as a NPL(National Priority List), ERNS (Emergency Response Notification System), CERCLIS (Comprehensive Environmental Response Compensation and Liability Information System), RCRIS (Resource Conservation And Recovery Information System), LPST (Leaking Underground Petroleum Storage Tanks), UST (Underground Petroleum Storage Tanks), TSD (Treatment, Storage, and Disposal) or a LANDFILL facility. Adjacent sites and sites within the half-mile radius are not listed as NPL (National Priority List), CERCLIS (Comprehensive Environmental Response Compensation and Liability Information System), ERNS (Emergency Response Notification System), RCRIS (Resource Conservation And Recovery Information System), UST (Underground Petroleum Storage Tanks), TSD (Treatment, Storage, and Disposal) and LANDFILL facilities.

Six facilities within the half-mile radius appear on the LPST (Leaking Underground Petroleum Storage Tanks) facilities list. Final concurrences were issued and the cases were closed for the facilities on 3002 Little York Rd., 10500A, 10555 and 10621 Eastex Freeway. Final concurrence is pending at the facility on 10603 Eastex Freeway. The facility on 3102 Little York Rd. is under risk assessment. The two listed facilities are not adjacent to the property and, therefore would not pose a contamination risk to the subject site.

The Phase 1 ESA based on the on-site inspection, review of the regulatory lists, inquiries with the local governmental agencies, review of the title search, and review of the aerial photos reveals that the site has a low risk with respect to the environmental concerns.

#### 2.0 OBJECTIVE

# 2.1 Scope of work

The scope of the study included a site visit, a review of the site history, regulatory agency documentation and an environmental assessment of the property.

#### 2.2 Client authorization

The study was authorized by Mr. Gabriel Mussio, Building Services Department, City of Houston, Houston, Texas and was performed for the client in evaluating potential environmental problems associated with the site. If any additional information is known or encountered regarding the site, it should be forwarded to this office for a possible reevaluation of conclusions.

#### 2.3 Limitations and assessment

The Phase I Environmental Site Assessment consists of various studies including a review of the chain of title of the property, an on-site inspection of the site and it's facilities, a review of the files at Government and Environmental Regulatory Agencies. All investigations in this study have been conducted in accordance with American Society for Testing and Materials and Standard Practice for Phase I Environmental Site Assessments.



Residential Area



Figure is an approximation

Figure1: Site map- 2900 Briarwick Ln., Houston, Texas 77093


Scale: 1" = 30 ft (approx.)

# 3.0 SITE LOCATION AND DESCRIPTION

The subject property is a vacant land and is 7, 650 square feet in area. The site has vacant, grassy areas. The site is legally described as follows:

"Lot 1, Block 11, Pinewood Village, Section 2, a subdivision located in the William J. Foster Survey, Abstract No. 279, Harris County, Texas, according to the map recorded in Volume 36, Page 22, Harris County Map Records".

The site is geographically located at Latitude 29° 52' 02" and Longitude 95° 20' 24". A site map is presented as Figure-1.



Site Topographic Map

#### 4.0 ENVIRONMENTAL SETTING

USGS Quadrangle Maps, Texas Water Development Board hyrogeological literature, conversations with the local officials and the Geologic Atlas of Texas were used to determine the environmental setting of the site and the general area.

#### 4.1 Surface water characteristics

The elevation of the site is approximately 60 feet Above Mean Sea Level (AMSL) and can be seen on the Settegast Quadrangle Map. Nearest surface water feature is Halls Bayou. Surface water drainage is to the southeast.

#### 4.2 Groundwater characteristics

Groundwater in the area is obtained from the Chicot and Evangeline aquifers. These units are composed of clay, sand and gravel which were deposited in the fluvial, deltaic, and shallow marine environments and are hydrologically connected. The Chicot aquifer consists of the Willis Sand, Bentley Formation and the Montgomery Formation, Beaumont Formation and overlies the Evangeline aquifer. The Evangeline aquifer consists of the upper most part of the Fleming Formation and the Goliad Sand.

Recharge to the aquifers is from precipitation that falls on the outcrop areas. These formations outcrop in belts that are nearly parallel to the Gulf of Mexico. The Goliad Sand is overlapped by younger formations east of the Brazos river and is not exposed at the surface in the coastal area.


The site is located on the Beaumont Formation which is of quaternary age and consists of mostly stream channel, point bar, natural levee, backswamp and to a lesser extent coastal marsh and mud flat deposits.



1 Mile Radius Single Map:



#### 2900 BRIARWICK LANE, HOUSTON TX 77093



Source: 2002 U.S. Census TIGER Files

Target Site (Latitude: 29.867306 Longitude: -95.34001) .... Identified Site, Multiple Sites, Receptor ....

NPL, Brownfield, Solid Waste Landfill (SWL) or Hazardous Waste




Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Radius



1 Mile Radius ASTM: NPL, RCRACOR, STATE



# 2900 BRIARWICK LANE, HOUSTON TX 77093



Source: 2002 U.S. Census TIGER Files

Target Site (Latitude: 29.867306 Longitude: -95.34001) ......

Identified Site, Multiple Sites, Receptor ...

NPL, Brownfield, Solid Waste Landfill (SWL) or Hazardous Waste




Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Radius



.5 Mile Radius ASTM: CERCLIS, RCRATSD, LUST, SWL



#### 2900 BRIARWICK LANE, HOUSTON TX 77093



Source: 2002 U.S. Census TIGER Files

Target Site (Latitude: 29.867306 Longitude: -95.34001) ..........

Identified Site, Multiple Sites, Receptor .....

NPL, Brownfield, Solid Waste Landfill (SWL) or Hazardous Waste

Railroads

Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft, Radius







.25 Mile Radius ASTM: NFRAP, RCRAGEN, ERNS, UST, OTHER



# 2900 BRIARWICK LANE, HOUSTON TX 77093



Source: 2002 U.S. Census TIGER Files

Target Site (Latitude: 29.867306 Longitude: -95.34001) ......

Identified Site, Multiple Sites, Receptor ......

NPL, Brownfield, Solid Waste Landfill (SWL) or Hazardous Waste

Railroad

Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Radius





#### 5.0 ENVIRONMENTAL REGULATORY REVIEW

Established lists were checked to evaluate if the site or adjacent properties are reported as having possible environmental concerns. The following paragraphs discuss the agencies and lists conducted.

#### 5.1 Federal and State Regulatory Agency Inquiries

#### NPL list

This is a list of sites established by Federal Government as having a priority for clean up.

Many are superfund sites. The site does not appear on the NPL list. Adjacent sites and sites within the half-mile radius do not appear on the list.

#### CERCLIS list

The CERCLIS list is compiled by the Federal Government and includes sites which could possibly be contaminated and may require clean up. Many of the sites which appear on the CERCLIS list have been thoroughly investigated. The site, adjacent sites and sites within the half-mile radius do not appear on the list.

#### **RCRIS FACILITIES list**

The Resource Conservation and Recovery Information System (RCRIS) is a nationwide data base created to maintain and regulate facilities that handle hazardous waste. The RCRIS data base replaced the HWDMS (Hazardous Waste Data Management System) in September 1992 as a major system supporting the implementation of RCRA (Resource Conservation and Recovery Act). The site does not appear on the list. Adjacent sites and sites within the half-mile radius do not appear on the CERCLIS facilities list.

#### TSD list

The TSD list consists of facilities that have been registered to treat, store or dispose of hazardous wastes. These facilities are assigned a corresponding TSD number. The site, adjacent properties and properties within the half-mile radius do not appear on the list.

#### **UST** list

Owners of Underground Storage Tanks (USTs) are required to register their USTs along with the construction information regarding the UST system with the Texas Commission on Environmental Quality (TCEQ). The property, adjacent properties and properties within the half-mile radius do not appear on the UST facilities list.

#### LPST list

The LPST list consists of Petroleum Storage Tank Systems which have reported releases of greater than 25 gallons. The list is maintained by the Texas Commission on Environmental Quality under delegation from the EPA. The property and adjacent properties do not appear on the list. Six facilities within the half-mile radius appear on the LPST facilities list. Final concurrences were issued and the cases were closed for the facilities on 3002 Little York Rd., 10500A, 10555 and 10621 Eastex Freeway. Final concurrence is pending at the facility on 10603 Eastex Freeway. The facility on 3102 Little York Rd., is under risk assessment. The two listed facilities are not adjacent to the property and, therefore would not pose a contamination risk to the subject site.

#### LANDFILL list

The landfill list is compiled and maintained by the Texas Department of Health and consists of sites identified as landfill, waste processing facility or sludge disposal facility. The site, adjacent properties and properties within the half-mile radius do not appear on the list.

#### ERNS list

EPA's emergency response notification system consists of a list of reported CERCLA hazardous substance releases or spills in quantities greater than the reportable quantity as maintained at the National Response Center. The site does not appear on the list. Adjacent sites and sites within the half-mile radius do not appear on the list.

#### 5.2 Other Local and State Government inquiries:

Harris County Pollution Control Department:

Ms. Fleda Key of the Harris County Pollution Control Department investigated the subject site for records of hazardous chemical spills. She indicated (ROC-1) that there were no chemical spills or accidental fires on record at the subject site during the last five (5) years.

#### 6.0 HISTORICAL USAGE INFORMATION

Site history was investigated by reviewing the property ownership information and aerial photos.

#### 6.1 Current ownership

Review of the title search indicates that the property is currently owned by City of Houston.

#### 6.2 Prior ownership

A copy of the title search is presented in Appendix-B. Review of the title search indicates that the property was never owned by the owners, whose names would indicate possible environmental concerns about the site, such as Landfill companies and Hazardous Waste Storage and Treatment and Disposal facilities. The property was owned by Reed-Yancey Realty in 1951. Since then, several companies and individuals owned the site. City of Houston acquired the site in the year 1961.

#### 6.3 Historical City Directories/ Fire Insurance Maps

Historical City Directories and Fire Insurance Maps were not available for this area.

#### 6.4 Review of the aerial photographs

1944 aerial photo (1"= 700') shows the site as a vacant land. Vacant and residential sites are present to the far north, south, east and the west.

1953 aerial photo (1"= 700') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

1969 aerial photo (1"= 700') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

1979 aerial photo (1"= 700') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

1986 aerial photo (1"= 700') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

1996 aerial photo (1"= 700') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

2004 aerial photo (1"= 700') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

#### 7.0 RESULTS OF THE ON-SITE INSPECTION

The site was inspected on December 29, 2005 by Mr. Zahir Jamal of RAO ENVIRONMENTAL.

#### 7.1 Observations

The subject property is a vacant land and is 7, 650 square feet in area. The property has vacant, grassy areas. Entrance to the site is from Briarwick Ln. and Royal Pine Dr. An electric pole is present to the south of the site. A partial fence of a house is present to the east of the site. There are no pipeline easements running through or located on adjacent boundaries of the site. No other developments or improvements were found at the site.

Vent lines, tankhold areas and steel caps indicative of the buried USTs were not found at the site.

Following is the list of property's usage at the adjacent properties.

Property usage-north:

Adjacent properties to the north are Briarwick Ln. and a residential

area.

Property usage-south:

Adjacent properties to the south are drainage drain and vacant land

with weeds, bushes and trees.

Property usage-east:

Adjacent property to the east is a residential area.

Property usage-west:

Adjacent properties to the west are Royal Pine Dr., residential area and

Pinewood Village Park.

#### 7.2 Hazardous substance identification/inventory

Pesticides, solvents and other hazardous materials were not found at the site.

#### 7.3 PCBs and Radon

PCB containing materials such as capacitors, transformers and light ballasts were not found at the sites. The sites are not in a EPA designated radon gas containing area. The soil at the subject sites, therefore, does not emit radon gas.

# 7.4 Lead Paint containing materials

The site is a vacant land.

# 7.5 Sampling results

The site is a vacant land.

# 8.0 FINDINGS AND CONCLUSIONS

The Phase 1 ESA based on the on-site inspection, review of the regulatory lists, inquiries with the local governmental agencies, review of the title search, and review of the aerial photos reveals that the site has a low risk with respect to the environmental concerns.

# 9.0 REFERENCES

- 1. Settegast Quadrangle, USGS Quadrangle Map.
- 2. Survey documents.
- 3. Texas Water Development Board, Report 310.
- 4. Geologic Atlas of Texas, Houston sheet.

Sincerely,

Rao Somepalli, Ph.D.

Project Manager

APPENDIX -A

#### RECORD OF COMMUNICATION

ROC-1

FROM: Ms. Fleda Key

Harris County Pollution Control Department

Tel #: 713-920-2831

TO: Rao Somepalli

DATE & TIME: January 03, 2006, 10:14 AM

SUMMARY OF COMMUNICATION:

There were no chemical spills on record at the subject site during the last five (5) years.

APPENDIX-B

# TEXAS ABSTRACT SERVICES 412 MAIN ST., SUITE 250 HOUSTON, TEXAS 77002

# HISTORICAL OWNERSHIP REPORT

January 3, 2006

Control No. 11650

Mr. Rao Somepali Rao Environmental Consultants

Re: 2900 Briarwick Lane, Houston, Texas 77093

SUBJECT PROPERTY: Lot 1, Block 11, Pinewood Village, Section 2, a subdivision located in the William J. Foster Survey, Abstract No. 279, Harris County, Texas, according to the map recorded in Volume 36, Page 22, Harris County Map Records.

Dear Mr. Somepali:

At your request, we have searched the records of the County Clerk of Harris County, Texas, pertaining to the property referenced above from January 1, 1955 to the present and have determined that the following list represents all of the deeds, surface leases and environmental liens of record within the said period.

DATE:

4-20-51

INSTRUMENT:

Map of Pinewood Village, Section 2

GRANTOR:

Reed-Yancey Realty Company

GRANTEE: COMMENTS: The Public 21.26 acres

REFERENCE:

36/22 Map Records

DATE:

2-14-51

INSTRUMENT:

Warranty Deed

GRANTOR: GRANTEE: Reed-Yancey Realty Company Pinewood Utilities Company

COMMENTS:

Lot 1

REFERENCE:

2228/666 Deed Records; corrected by 4109/180 Deed Records

Continued

Page 2

DATE:

6-30-61

INSTRUMENT:

Warranty Deed

GRANTOR:

Pinewood Utilities Company

GRANTEE:

City of Houston

COMMENTS:

Lot 1

REFERENCE:

B356393


Current through December 27, 2005

Texas Abstract Services disclaims any warranties, expressed or implied concerning this information. Texas Abstract Services' liability for errors or omissions in this information shall be limited to the amount paid for this report. By accepting this form, the party requesting the information agrees that the disclaimer of warranties and liability limitation contained in this paragraph is a part of its contract with Texas Abstract Services and shall cover all actions whether arising hereunder by statue, in contract of in tort.

TEXAS ABSTRACT SERVICES

ce might foot

Jessica M. Lightfoot



APPENDIX-C



Banks Information Solutions, Inc.

# **Environmental FirstSearch™ Report**

TARGET PROPERTY:

# 2900 BRIARWICK LANE

# **HOUSTON TX 77093**

Job Number: 31196

# PREPARED FOR:

Rao Environmental 19333 Hwy 59 North, Ste. 190 Humble, TX 77338



Tel: (512) 478-0059

Fax: (512) 478-1433

# Environmental FirstSearch Site Information Report

Request Date:

01-03-06

Requestor Name:

Rao

Standard:

**ASTM** 

Search Type:

COORD

Job Number:

31196

Filtered Report

TARGET ADDRESS: 2900 BRIARWICK LANE

**HOUSTON TX 77093** 

# Demographics

Sites:

8

Non-Geocoded: 0

Population: NA

Radon: NA

# Site Location

Degrees	(Decimal)
0. 100	

Degrees (Min/Sec)

**UTMs** 

Longitude:

-95.34001

-95:20:24

Easting:

273975.355

Latitude:

29.867306

29:52:2

Northing:

3306201.742

Zone:

15

# Comment

Comment:

# Additional Requests/Services

Adjacent ZIP Codes: 0 Mile(s)

Services:

ty Name	ST	Dist/Dir
ty Name	- 81	Dist/Dir
	y Name	ty Name ST

	Requested?	Date
Sanborns	No	
Aerial Photographs	No	
Historical Topos	No	
City Directories	No	
Title Search	No	
Municipal Reports	No	
Online Topos	No	

# Environmental FirstSearch Search Summary Report

**Target Site:** 2900 BRIARWICK LANE HOUSTON TX 77093

FirstSearch Summary

Database	Sel	Updated	Radius	Site	1/8	1/4	1/2	1/2>	ZIP	TOTALS
NPL	Y	10-07-05	1.00	0	0	0	0	0	0	0
CERCLIS	Y	10-07-05	0.50	0	0	0	0	2	0	0
NFRAP	Y	08-01-05	0.25	0	0	0	-	-	0	0
RCRA TSD	Y	09-22-05	0.50	0	0	0	0	2	0	0
RCRA COR	Y	09-22-05	1.00	0	0	0	0	1	0	1
RCRA GEN	Y	06-13-05	0.25	0	0	0	-	_	0	0
ERNS	Y	12-31-04	0.25	0	0	0	-		0	0
State Sites	Y	01/05/05	1.00	0	0	0	0	0	0	0
SWL	Y	09-16-02	0.50	0	0	0	0	-	0	0
Other	Y	06/27/05	0.25	0	0	1	-	=	0	1
REG UST/AST	Y	07/13/05	0.25	0	0	0	-	-	0	0
Leaking UST	Y	06/27/05	0.50	0	0	0	6	-	0	6
- TOTALS -				0	0	1	6	1	0	8

#### Notice of Disclaimer

Due to the limitations, constraints, inaccuracies and incompleteness of government information and computer mapping data currently available to Banks Information Solutions, Inc., certain conventions have been utilized in preparing the locations of all federal, state and local agency sites residing in Banks Information Solutions, Inc.'s databases. All EPA NPL and state landfill sites are depicted by a rectangle approximating their location and size. The boundaries of the rectangles represent the eastern and western most longitudes; the northern and southern most latitudes. As such, the mapped areas may exceed the actual areas and do not represent the actual boundaries of these properties. All other sites are depicted by a point representing their approximate address location and make no attempt to represent the actual areas of the associated property. Actual boundaries and locations of individual properties can be found in the files residing at the agency responsible for such information.

#### Waiver of Liability

Although Banks Information Solutions, Inc. uses its best efforts to research the actual location of each site, Banks Information Solutions, Inc. does not and can not warrant the accuracy of these sites with regard to exact location and size. All authorized users of Banks Information Solutions, Inc.'s services proceeding are signifying an understanding of Banks Information Solutions, Inc.'s searching and mapping conventions, and agree to waive any and all liability claims associated with search and map results showing incomplete and or inaccurate site locations.

# Environmental FirstSearch Sites Summary Report

TARGET SITE:

2900 BRIARWICK LANE

HOUSTON TX 77093

**JOB:** 31196

TOTAL: 8

GEOCODED: 8

NON GEOCODED: 0

SELECTED: 0

Map ID	DB Type	Site Name/ID/Status	Address	Dist/Dir	Page No.	
6	LUST	MUFFLER KING 110787	3002 LITTLE YORK HOUSTON TX 77079	0.27 NE	T.	
7	LUST	JEFFYS QUICK STOP 101814	3102 LITTLE YORK RD HOUSTON TX 77000	0.37 NE	5	4 7
8	LUST	TXDOT HOUSTON ROW 098992	10603 EASTEX FWY HOUSTON TX 77093	0.47 SE	11	
3	LUST	TEJAS MOTOR CO 110435	10555 EASTEX FWY HOUSTON TX 77093	0.47 SE	12	
5	LUST	FAST STOP 46 104553	10621 EASTEX FRWY HOUSTON TX 77093	0.48 SE	16	
4	LUST	SAUNDERS ROAD TEXACO 103841	10500A EASTEX FWY HOUSTON TX 77093	0.50 SE	19	
2	OTHER	ALL AROUND VACUME SERVICE IHW-49111/INACTIVE	10759 ROYAL PINE DRIVE HOUSTON TX 77093	0.16 NW	22	
1	RCRACOR	PORTAWASH SYSTEMS INC TXD982561375/CA	3425 MOHAWK ST HOUSTON TX 77093	0.80 NE	23	

# Environmental FirstSearch Site Detail Report

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS						
SEARCH	ID: 5	DIST/DIR:	0.27 NE	MAP ID: 6		
NAME: ADDRESS:	MUFFLER KING 3002 LITTLE YORK		REV:	06/27/05		
ADDRESS:	HOUSTON TX 77093 HARRIS		ID1: ID2: STATUS:	110787 0067482		
CONTACT:	HAROLD TURBOFF		PHONE:	713/721-7296		

#### SITE INFORMATION

REPORTED: 4/5/1996 ENTERED INTO SYSTEM: 4/9/1996

SITE PRIORITY: gw impacted, no apparent threats or impacts to receptors

SITE STATUS: Final concurrence issued, case close

PRP: PRIME CAPITOL

PRP ADDRESS: 11246 S POST OAK STE 300 HOUSTON TX 77035 PRP CONTACT: HAROLD TURBOFF PRP PHONE: 713/721-7296

#### LUST INFORMATION

TANK NUMBER: STATUS:

Removed From Ground STATUS DATE: 03291996 INSTALL DATE: 08311987 REGISTERED DATE: 12061995

CAPACITY: 0002000 Gallons Single Wall -EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION: - None

CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported

STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS:

Not Reported

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE: PIPE MATERIAL: Steel PIPE DESIGN EXT CONTAINMENT: Single Wall -

PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: GASOLINE TANK RLSE DETECTION METHODS: - - - None TANK RLSE DETECTION VARIANCE: No Variance PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE: No Variance

SPILL/OVERFILL PREVENTION: - Continued on next page -SPILL/OVERFILL VARIANCE: No Variance

# Environmental FirstSearch Site Detail Report

TARGET SITE: 2900 BRIARWICK LANE HOUSTON TX 77093

**JOB:** 31196

LEAKING UNDERGROUND STORAGE TANKS				
SEARCH ID: 5	DIST/DIR:	0.27 NE	MAP ID: 6	
NAME: MUFFLER KING		REV:	06/27/05	
ADDRESS: 3002 LITTLE YORK		ID1:	110787	
HOUSTON TX 77093		ID2:	0067482	
HARRIS		STATUS:		
CONTACT: HAROLD TURBOFF		PHONE:	713/721-7296	
TANK NUMBER:	2			
STATUS:	Removed From Ground			
STATUS DATE:	03291996			
INSTALL DATE:	08311987			
REGISTERED DATE:	12061995			
CAPACITY:	0002000 Gallons			
EXT CONTAINMENT DESIGN:	Single Wall -			
CONSTRUCTION MATERIAL:	Steel			
CORROSION PROTECTION:	-			
	- None			
CORROSION PROT VARIANCE:	No Variance			
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported			
STG 1 EQUIP INSTALL DATE:	110t Reported			
STG 2 VAPOR RECOVERY EQUIP STATUS:	Not Reported			
STG 2 EQUIP INSTALL DATE:	Not Reported			
INSTALLER COMPANY:				
INSTALLER NAME:				
INSTALLER LICENSE NUMBER:				
TYPE OF PIPE:				
PIPE MATERIAL:	Steel			
PIPE DESIGN EXT CONTAINMENT:	Single Wall -			
PIPE CONECTORS & VALVES:				
PIPE CORROSION PROTECTION:	-			
	2 <b>4</b> 00			
PIPE CORROSION PROT VARIANCE:	No Variance			
SUBSTANCE STORED:	GASOLINE			
TANK RLSE DETECTION METHODS:	None			
TANK RLSE DETECTION VARIANCE:	No Variance			
PIPE RLSE DETECTION METHODS:				
PIPE RLSE VARIANCE:	No Variance			
SPILL/OVERFILL PREVENTION:				
SPILL/OVERFILL VARIANCE:	No Variance			
ΓANK NUMBER:	3			
STATUS:	Removed From Ground			
STATUS DATE:	03291996			
INSTALL DATE:	08311987			
REGISTERED DATE:	12061995			
CAPACITY:	0002000 Gallons			
EXT CONTAINMENT DESIGN:	Single Wall -			
CONCERNICATION MATERIAL				
CONSTRUCTION MATERIAL: CORROSION PROTECTION:	Steel			

# Environmental FirstSearch Site Detail Report

TARGET SITE: 2900 BRIARWICK LANE HOUSTON TX 77093

**JOB:** 31196

LEAKING UNDERGROUND STORAGE TANKS					
SEARCH ID: 5	DIST/DIR:	0.27 NE	MAP ID:	5	
NAME: MUFFLER KING		DEV.	06/27/05		
NAME: MUFFLER KING ADDRESS: 3002 LITTLE YORK		REV: ID1:	06/27/05 110787		
HOUSTON TX 77093		ID1:	0067482		
HARRIS		STATUS:	0007482		
CONTACT: HAROLD TURBOFF		PHONE:	713/721-7296		
CORROSION BROT VARIANCE	N. W.				
CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EOUIP STATUS:	No Variance				
	Not Reported				
STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS:	Not Reported				
STG 2 EQUIP INSTALL DATE:	Not reported				
NSTALLER COMPANY:					
NSTALLER NAME:					
NSTALLER LICENSE NUMBER:					
TYPE OF PIPE:					
PIPE MATERIAL:	Steel				
PIPE DESIGN EXT CONTAINMENT:	Single Wall -				
PIPE CONECTORS & VALVES:					
PIPE CORROSION PROTECTION:					
PIPE CORROSION PROT VARIANCE:	No Variance				
SUBSTANCE STORED:	GASOLINE				
TANK RLSE DETECTION METHODS:	None				
TANK RESE DETECTION VARIANCE:	No Variance				
PIPE RLSE DETECTION METHODS:					
PIPE RLSE VARIANCE:	No Variance				
SPILL/OVERFILL PREVENTION:					
SPILL/OVERFILL VARIANCE:	No Variance				
TANK NUMBER:	4				
STATUS:	Removed From Ground				
STATUS DATE:	03291996				
NSTALL DATE:	08311987				
REGISTERED DATE:	12061995				
CAPACITY:	0000000 Gallons				
EXT CONTAINMENT DESIGN:	Single Wall -				
CONSTRUCTION MATERIAL:	Steel				
CORROSION PROTECTION:	· Name				
CORROSION BROT VARIANCE.	- None				
CORROSION PROT VARIANCE:	No Variance				
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported				
STG 1 EQUIP INSTALL DATE:	Not Donostad				
STG 2 VAPOR RECOVERY EQUIP STATUS: STG 2 EQUIP INSTALL DATE:	Not Reported				
516 2 EQUIT INSTALL DATE:					
NSTALLER COMPANY:					
NSTALLER NAME:					
NSTALLER LICENSE NUMBER:					
TVPE OF PIPE.					
TYPE OF PIPE: PIPE MATERIAL:	Steel				
PIPE DESIGN EXT CONTAINMENT:	Single Wall	- C	ontinued on next page -		

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

LEAKING UNDERGROUND STORAGE TANKS					
SEARCH ID: 5	DIST/DIR:	0.27 NE	MAP ID: 6		
NAME: MUFFLER KING		REV:	06/27/05		
ADDRESS: 3002 LITTLE YORK		ID1:	110787		
HOUSTON TX 77093		ID2:	0067482		
HARRIS		STATUS	:		
CONTACT: HAROLD TURBOFF		PHONE:	713/721-7296		
PIPE CONECTORS & VALVES:					
PIPE CORROSION PROTECTION:	-				
PIPE CORROSION PROT VARIANCE:	No Variance				
SUBSTANCE STORED:	GASOLINE				
TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE:	None No Variance				
PIPE RLSE DETECTION WARRANCE:	No variance				
PIPE RLSE VARIANCE:	No Variance				
SPILL/OVERFILL PREVENTION:					
SPILL/OVERFILL VARIANCE:	No Variance				
TANK NUMBER:	5				
STATUS:	Removed From Ground				
STATUS DATE:	03291996				
INSTALL DATE:	08311987				
REGISTERED DATE:	12061995				
CAPACITY: EXT CONTAINMENT DESIGN:	0000500 Gallons				
EXT CONTAINMENT DESIGN:	Single Wall -				
CONSTRUCTION MATERIAL:	Steel				
CORROSION PROTECTION:					
	- None				
CORROSION PROT VARIANCE:	No Variance				
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported				
STG 1 EQUIP INSTALL DATE:					
STG 2 VAPOR RECOVERY EQUIP STATUS:					
STG 2 EQUIP INSTALL DATE:					
INSTALLER COMPANY:					
INSTALLER NAME:					
INSTALLER LICENSE NUMBER:					
TYPE OF PIPE:					
PIPE MATERIAL:	Steel				
PIPE DESIGN EXT CONTAINMENT:	Single Wall -				
PIPE CONECTORS & VALVES:	36.00				
PIPE CORROSION PROTECTION:	-				
PIPE CORROSION PROT VARIANCE:	No Variance				
SUBSTANCE STORED:	USED OIL				
TANK RLSE DETECTION METHODS:	None				
TANK RLSE DETECTION VARIANCE:	No Variance				
PIPE RLSE DETECTION METHODS:	5.5.				
PIPE RLSE VARIANCE:	No Variance				
SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:	No Variance		Value con a company and a company of the company		
STILL OVERFILL VARIANCE:	140 variance		- Continued on next page -		

TARGET SITE: 2900 BRIARWICK LANE HOUSTON TX 77093

LEAKING UNDERGROUND STORAGE TANKS					
SEARCH ID: 5	DIST/DIR:	0.27 NE	MAP ID:	6	
NAME: MUFFLER KING		REV:	06/27/05		
ADDRESS: 3002 LITTLE YORK		ID1:	110787		
HOUSTON TX 77093		ID2:	0067482		
HARRIS		STATUS:			
CONTACT: HAROLD TURBOFF		PHONE:	713/721-7296		

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

#### LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID:

DIST/DIR:

0.37 NE

MAP ID:

NAME: ADDRESS: JEFFYS QUICK STOP 3102 LITTLE YORK RD

HOUSTON TX 77093 HARRIS

REV: ID1:

06/27/05 101814

ID2: STATUS: 0041540

PHONE:

281/376-2040

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

CONTACT: ASSAD BOULOS

SITE PRIORITY:

10/17/1991 2/19/1992

SITE STATUS: PRP:

gw impacted, no apparent threats or impacts to receptors Plan / Risk assessment

MR RIAD SAIDI

PRP ADDRESS: PRP CONTACT:

PRP PHONE:

12327 NEW HAMPTON TOMBALL TX 77375 ASSAD BOULOS 281/376-2040

LUST INFORMATION

TANK NUMBER:

STATUS:

Removed From Ground

STATUS DATE: INSTALL DATE: REGISTERED DATE: 08312001 01291979 05081986

CAPACITY: EXT CONTAINMENT DESIGN: 0004000 Gallons Single Wall -

CONSTRUCTION MATERIAL:

Steel

CORROSION PROTECTION:

Ext Dielectric Coating/Laminate/Tape/Wrap -

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

No Variance Not Reported

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

Single Wall -

PIPE CONECTORS & VALVES:

Ext Dielectric Coating/Laminate/Tape/Wrap -

PIPE CORROSION PROTECTION:

No Variance

SUBSTANCE STORED:

GASOLINE

TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE:

PIPE CORROSION PROT VARIANCE:

Groundwater Monitoring - - - Inventory Control No Variance

PIPE RLSE DETECTION METHODS:

Groundwater Monitoring - Auto Leak Line Detector (3.0gph for pressure piping) - -

PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION:

Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Office al you APRY purge tory Built

Spill Container/Bucket/Sump

TANK NUMBER: STATUS:

STATUS DATE:

INSTALL DATE:

REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

TARGET SITE: 2900 BRIARWICK LANE

JOB: 31196

LEAKING UNDERGROUND STORAGE TANKS						
SEARCH ID: 4	DIST/DIR: 0.37 NE		MAP ID: 7			
NAME: JEFFYS QUICK STOP			REV:	06/27/05		
ADDRESS: 3102 LITTLE YORK RD			ID1:	101814		
HOUSTON TX 77093 HARRIS			ID2: STATUS:	0041540		
CONTACT: ASSAD BOULOS			PHONE:	281/376-2040		
SPILL/OVERFILL VARIANCE:	No Variance					
TANK NUMBER:	4					
STATUS:	Removed From Ground					
STATUS DATE:	08312001					
INSTALL DATE:	08311987					
REGISTERED DATE:	05081986					
CAPACITY:	0004000 Gallons					
EXT CONTAINMENT DESIGN:	Single Wall -					
CONSTRUCTION MATERIAL:	Steel					
CORROSION PROTECTION:	Ext Dielectric Coating/Lami	inate/Tane/	Wran			
comosion norderion.	-	mater raper	wrap			
CORROSION PROT VARIANCE:	No Variance					
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported					
STG 1 EQUIP INSTALL DATE:						
STG 2 VAPOR RECOVERY EQUIP STATUS:						
STG 2 EQUIP INSTALL DATE:						
INSTALLER COMPANY:						
INSTALLER NAME:						
INSTALLER LICENSE NUMBER:						
TYPE OF PIPE:						
PIPE MATERIAL:	Steel					
PIPE DESIGN EXT CONTAINMENT:	Single Wall					
PIPE CONECTORS & VALVES:	2-1-1					
PIPE CORROSION PROTECTION:	-					
	- None					
PIPE CORROSION PROT VARIANCE:	No Variance					
SUBSTANCE STORED:	GASOLINE					
TANK RLSE DETECTION METHODS:	Groundwater Monitoring -	Invento	ry Control			
TANK RLSE DETECTION VARIANCE:	No Variance					
PIPE RLSE DETECTION METHODS:	Groundwater Monitoring - A	Auto Leak I	Line Detector (3	.0gph for pressure	piping)	
Tightness Testing						
PIPE RLSE VARIANCE:	No Variance					
SPILL/OVERFILL PREVENTION:	Auto Flow Restrictor Valve	(AFRV) -	Auto Delivery S	hut Off Valve (AI	OSV) - Factor	y Built
Spill Container/Bucket/Sump	No Verlence					
SPILL/OVERFILL VARIANCE:	No Variance					
TANK MUMBED.	2					

Removed From Ground

08312001

08311987 05081986

0004000 Gallons

Single Wall -

- Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 4

DIST/DIR:

0.37 NE

MAP ID:

NAME: ADDRESS:

JEFFYS QUICK STOP 3102 LITTLE YORK RD

HOUSTON TX 77093

HARRIS CONTACT: ASSAD BOULOS

REV: ID1: ID2:

06/27/05 101814

0041540

STATUS: PHONE:

281/376-2040

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

Steel

No Variance

Not Reported

Ext Dielectric Coating/Laminate/Tape/Wrap -

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY: INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

Steel

PIPE DESIGN EXT CONTAINMENT:

Single Wall -

PIPE CONECTORS & VALVES:

PIPE CORROSION PROTECTION:

- None No Variance

GASOLINE

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS:

Groundwater Monitoring - - - Inventory Control

TANK RLSE DETECTION VARIANCE:

PIPE CORROSION PROT VARIANCE:

No Variance

PIPE RLSE DETECTION METHODS:

Groundwater Monitoring - Auto Leak Line Detector (3.0gph for pressure piping) - -

Tightness Testing

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built

Spill Container/Bucket/Sump

SPILL/OVERFILL VARIANCE:

No Variance

TANK NUMBER:

STATUS:

Removed From Ground

STATUS DATE: INSTALL DATE: 08312001 01011979 05081986

REGISTERED DATE: CAPACITY:

0012000 Gallons Single Wall -

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: CORROSION PROTECTION:

Ext Dielectric Coating/Laminate/Tape/Wrap -

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

No Variance Not Reported

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 4

DIST/DIR:

0.37 NE

MAP ID:

NAME: ADDRESS: JEFFYS QUICK STOP 3102 LITTLE YORK RD

HOUSTON TX 77093

REV: ID1: ID2:

06/27/05 101814 0041540

HARRIS

CONTACT: ASSAD BOULOS

STATUS: PHONE:

281/376-2040

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

Steel

PIPE DESIGN EXT CONTAINMENT:

Single Wall -

PIPE CONECTORS & VALVES:

PIPE CORROSION PROTECTION:

- None

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED:

DIESEL

TANK RLSE DETECTION METHODS:

Groundwater Monitoring - - - Inventory Control

TANK RLSE DETECTION VARIANCE:

No Variance

PIPE RLSE DETECTION METHODS:

Groundwater Monitoring - Auto Leak Line Detector (3.0gph for pressure piping) - -

**Tightness Testing** PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION:

Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built

Spill Container/Bucket/Sump

SPILL/OVERFILL VARIANCE:

No Variance

TANK NUMBER:

STATUS:

Removed From Ground

STATUS DATE: INSTALL DATE: 08312001 01011979

REGISTERED DATE:

05081986 0012000 Gallons

CAPACITY: EXT CONTAINMENT DESIGN:

Single Wall -

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

Ext Dielectric Coating/Laminate/Tape/Wrap -

CORROSION PROT VARIANCE:

No Variance

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

Not Reported

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

Steel

PIPE DESIGN EXT CONTAINMENT:

Single Wall -

PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION:

- None

PIPE CORROSION PROT VARIANCE:

No Variance

SUBSTANCE STORED:

GASOLINE

- Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE

HOUSTON TX 77093

JOB: 31196

LEAKING UNDERGROUND STORAGE TANKS					
SEARCH ID: 4	DIST/DIR:	0.37 NE	MAP ID: 7		
NAME: JEFFYS QUICK STOP		REV:	06/27/05		
ADDRESS: 3102 LITTLE YORK RD		ID1:	101814		
HOUSTON TX 77093		ID2:	0041540		
HARRIS		STATUS:	0071270		
CONTACT: ASSAD BOULOS		PHONE:	281/376-2040		
TANK RLSE DETECTION METHODS:	Groundwater Monitoring -	Inventory Control			
TANK RLSE DETECTION VARIANCE:	No Variance				
PIPE RLSE DETECTION METHODS:		Auto Leak Line Detector (	3.0gph for pressure piping)		
Fightness Testing			and breams bring)		
PIPE RLSE VARIANCE:	No Variance				
SPILL/OVERFILL PREVENTION:		(AFRV) - Auto Delivery	Shut Off Valve (ADSV) - Factory Built		
Spill Container/Bucket/Sump	. Ideo I for redifictor 7 dive	( iv ) Time Delivery	onar on rune (ribor) - ruetory built		
SPILL/OVERFILL VARIANCE:	No Variance				
THE STEM HER TANIANCES	110 Turinico				
TANK NUMBER:	6				
STATUS:	Removed From Ground				
STATUS DATE:	03251993				
INSTALL DATE:					
REGISTERED DATE:	05081986				
CAPACITY:	0000550 Gallons				
EXT CONTAINMENT DESIGN:	Single Wall -				
CONSTRUCTION MATERIAL:	Steel				
CORROSION PROTECTION:					
	- None				
CORROSION PROT VARIANCE:	No Variance				
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported				
STG 1 EQUIP INSTALL DATE:					
STG 2 VAPOR RECOVERY EQUIP STATUS:	Not Reported				
STG 2 EQUIP INSTALL DATE:					
INSTALLER COMPANY:					
INSTALLER NAME:					
INSTALLER LICENSE NUMBER:					
TYPE OF PIPE:	Suction				
PIPE MATERIAL:	Steel				
PIPE DESIGN EXT CONTAINMENT:	Single Wall				
PIPE CONECTORS & VALVES:					
PIPE CORROSION PROTECTION:					
	- None				
PIPE CORROSION PROT VARIANCE:	No Variance				
SUBSTANCE STORED:	GASOLINE				
TANK RLSE DETECTION METHODS:					
	None				
FANK RLSE DETECTION VARIANCE:	No Variance				
PIPE RLSE DETECTION METHODS:	None				
PIPE RLSE VARIANCE:	No Variance				
SPILL/OVERFILL PREVENTION:					
SPILL/OVERFILL VARIANCE:	No Variance				
TANK NUMBER:	7				
STATUS:	Removed From Ground		Continued on next page -		
STATUS DATE:	03251993	- 0	ommun on new page -		

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

06/27/05

0041540

281/376-2040

101814

31196

LEAKING	UNDERGROUND	STORAGE	TANKS

SEARCH ID: 4

DIST/DIR:

0.37 NE

REV:

ID1:

ID2:

STATUS:

PHONE:

MAP ID:

7

NAME:

INSTALL DATE: REGISTERED DATE:

JEFFYS QUICK STOP ADDRESS: 3102 LITTLE YORK RD

**HOUSTON TX 77093** 

HARRIS

CONTACT: ASSAD BOULOS

05081986

CAPACITY: EXT CONTAINMENT DESIGN:

0000550 Gallons

Single Wall -

No Variance

Not Reported

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

Steel - None

CORROSION PROT VARIANCE:

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS & VALVES:

PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

Gravity Steel

Single Wall -

- None No Variance

**USED OIL** 

- - - None

No Variance

No Variance

SUBSTANCE STORED:

TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE:

- - - None No Variance

SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE:

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 8

DIST/DIR:

0.47 SE

MAP ID:

NAME:

TXDOT HOUSTON ROW

ADDRESS:

10603 EASTEX FWY HOUSTON TX 77093

HARRIS CONTACT: DON HILL

06/27/05 098992

ID1: ID2:

REV:

STATUS:

PHONE:

512/416-3009

SITE INFORMATION

REPORTED:

5/7/1991

ENTERED INTO SYSTEM:

SITE PRIORITY:

no gw impacted, no apparent threats or impacts to receptors

SITE STATUS:

Final concurrence pending documentation of well plugging

PRP:

TXDOT

PRP ADDRESS:

125 E 11th ST AUSTIN TX 78701

PRP CONTACT:

DON HILL

PRP PHONE:

512/416-3009

LUST INFORMATION

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS SEARCH ID: DIST/DIR: 0.47 SE MAP ID: 3

TEJAS MOTOR CO NAME: ADDRESS: 10555 EASTEX FWY

HOUSTON TX 77093

HARRIS CONTACT: LESLIE WALKER REV: ID1:

06/27/05 110435 0023332

STATUS: PHONE:

ID2:

713/699-9865

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY: SITE STATUS:

no gw impacted, no apparent threats or impacts to receptors

Final concurrence issued, case close

PRP: PRP ADDRESS:

TEJAS MOTOR CO 10555 EASTEX FWY HOUSTON TX 77093 LESLIE WALKER PRP CONTACT: PRP PHONE: 713/699-9865

LUST INFORMATION

TANK NUMBER:

STATUS: Removed From Ground STATUS DATE: 01221996

INSTALL DATE: 01011960 REGISTERED DATE: 05081986 CAPACITY: 0000550 Gallons

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION:

CORROSION PROT VARIANCE: No Variance

STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL: Steel PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION:

- None

Not Reported

PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: USED OIL TANK RLSE DETECTION METHODS: - - - None TANK RLSE DETECTION VARIANCE: No Variance PIPE RLSE DETECTION METHODS: - - - None PIPE RLSE VARIANCE: No Variance

SPILL/OVERFILL PREVENTION:

SPILL/OVERFILL VARIANCE: No Variance - Continued on next page -

TARGET SITE:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

2900 BRIARWICK LANE HOUSTON TX 77093

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS SEARCH ID: DIST/DIR: 0.47 SE MAP ID: TEJAS MOTOR CO NAME: 06/27/05 REV: ADDRESS: 10555 EASTEX FWY ID1: 110435 HOUSTON TX 77093 0023332 ID2: HARRIS STATUS: CONTACT: LESLIE WALKER 713/699-9865 PHONE: TANK NUMBER: STATUS: Removed From Ground STATUS DATE: 01221996 INSTALL DATE: 01011960 REGISTERED DATE: 05081986 CAPACITY: 0004000 Gallons EXT CONTAINMENT DESIGN: CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION: CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 2 EQUIP INSTALL DATE: INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER: TYPE OF PIPE: PIPE MATERIAL: Steel PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION: - None PIPE CORROSION PROT VARIANCE: No Variance SUBSTANCE STORED: GASOLINE TANK RLSE DETECTION METHODS: - - - None No Variance TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: - - - None PIPE RLSE VARIANCE: No Variance SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE: No Variance TANK NUMBER: Removed From Ground STATUS: STATUS DATE: 01221996 INSTALL DATE: 01011960 05081986 REGISTERED DATE: CAPACITY: 0004000 Gallons EXT CONTAINMENT DESIGN:

Steel

- Continued on next page -

TARGET SITE: 2900 BRIARWICK LANE

**HOUSTON TX 77093** 

LEAKING UNDERGROUND STORAGE TANKS								
SEARCH ID:	7	<b>DIST/DIR:</b> 0.47 S		0.47 SE M		MAP ID:	MAP ID: 3	
NAME: TEJAS	MOTOR CO			DEV.	06/27/05			
ADDRESS: 10555				REV: ID1:	06/27/05 110435			
	TON TX 77093			ID2:	0023332			
HARR				STATUS:				
CONTACT: LESLI	E WALKER			PHONE:	713/699-9	865		
CORROSION PROT	VARIANCE:	No Variance						
STG 1 VAPOR REC	OVERY EQUIP STATUS:	Not Reported						
STG 1 EQUIP INST.								
	OVERY EQUIP STATUS:	Not Reported						
STG 2 EQUIP INST.	ALL DATE:							
INSTALLER COMP	ANY:							
INSTALLER NAME	:							
INSTALLER LICEN	SE NUMBER:							
TYPE OF PIPE:								
PIPE MATERIAL:		Steel						
PIPE DESIGN EXT	CONTAINMENT:	253						
PIPE CONECTORS	& VALVES:							
PIPE CORROSION	PROTECTION:							
		- None						
PIPE CORROSION	PROT VARIANCE:	No Variance						
SUBSTANCE STOR	ED:	GASOLINE						
	CTION METHODS:	None						
	CTION VARIANCE:	No Variance						
PIPE RLSE DETEC	TION METHODS:	None						
PIPE RLSE VARIA	NCE:	No Variance						
SPILL/OVERFILL I	PREVENTION:							
SPILL/OVERFILL V	ARIANCE:	No Variance						
TANK NUMBER:		4						
STATUS:		Removed From Ground						
STATUS DATE:		01221996						
INSTALL DATE:		01011960						
REGISTERED DAT	E:	05081986						
CAPACITY:		0004000 Gallons						
EXT CONTAINMEN	NT DESIGN:							
CONSTRUCTIONS	(ATEDIA)	Ct. 1						
CONSTRUCTION N		Steel						
CORROSION PROT	ECTION:							
CORROSION PROT	VARIANCE:	No Variance						
	OVERY EQUIP STATUS:	Not Reported						
STG 1 EQUIP INST.		reported						
	OVERY EQUIP STATUS:	Not Reported						
STG 2 EQUIP INST.								
INSTALLER COMP	ANY:							
INSTALLER NAME								
INSTALLER LICEN								
TYPE OF PIPE:								
PIPE MATERIAL:	,	Steel						
	CONTAINMENT:			- 0	onunuea o	n next page -		

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

LEAKING UNDERGROUND STORAGE TANKS					
SEARCH ID: 7	DIST/DIR: 0.47 SE		MAP ID: 3		
NAME TELLS MOTOR GO			0.0000		
NAME: TEJAS MOTOR CO		REV:	06/27/05		
ADDRESS: 10555 EASTEX FWY HOUSTON TX 77093		ID1: ID2:	110435		
HARRIS		STATUS:	0023332		
CONTACT: LESLIE WALKER		PHONE:	713/699-9865		
PIPE CONECTORS & VALVES:	12/27				
PIPE CORROSION PROTECTION:					
THE CORROSION I ROTECTION.	- None				
PIPE CORROSION PROT VARIANCE:	No Variance				
SUBSTANCE STORED:	GASOLINE				
TANK RLSE DETECTION METHODS:	None				
TANK RESE DETECTION METHODS: TANK RESE DETECTION VARIANCE:	No Variance				
PIPE RLSE DETECTION WARRANCE:	None				
PIPE RLSE VARIANCE:	No Variance				
SPILL/OVERFILL PREVENTION:	No variance				
SPILL/OVERFILL VARIANCE:	No Variance				
TANK NUMBER:	3				
STATUS:	Removed From Ground				
STATUS DATE:	01221996				
INSTALL DATE:	01011960				
REGISTERED DATE:	05081986				
CAPACITY:	0004000 Gallons				
EXT CONTAINMENT DESIGN:	-				
CONSTRUCTION MATERIAL:	Steel				
CORROSION PROTECTION:	*				
	*				
CORROSION PROT VARIANCE:	No Variance				
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported				
STG 1 EQUIP INSTALL DATE:					
STG 2 VAPOR RECOVERY EQUIP STATUS:	Not Reported				
STG 2 EQUIP INSTALL DATE:					
INSTALLER COMPANY:					
INSTALLER NAME:					
INSTALLER LICENSE NUMBER:					
TYPE OF PIPE:					
PIPE MATERIAL:	Steel				
PIPE DESIGN EXT CONTAINMENT:	- i				
PIPE CONECTORS & VALVES:					
PIPE CORROSION PROTECTION:					
	- None				
PIPE CORROSION PROT VARIANCE:	No Variance				
SUBSTANCE STORED:	GASOLINE				
TANK RLSE DETECTION METHODS:	None				
TANK RLSE DETECTION VARIANCE:	No Variance				
	None				
PIPE RUSE DE LECTION METHODS:	110110				
PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:	No Variance				
PIPE RESE DETECTION METHODS: PIPE RESE VARIANCE: SPILL/OVERFILE PREVENTION:	No Variance				

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS SEARCH ID: 7 DIST/DIR: 0.47 SE MAP ID: 3 NAME: TEJAS MOTOR CO REV: 06/27/05 ADDRESS: 10555 EASTEX FWY ID1: 110435 HOUSTON TX 77093 ID2: 0023332 HARRIS STATUS: CONTACT: LESLIE WALKER PHONE: 713/699-9865

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 3

DIST/DIR:

0.48 SE

MAP ID:

5

NAME:

FAST STOP 46

ADDRESS: 10621 EASTEX FRWY

HARRIS

**HOUSTON TX 77093** 

CONTACT: SUNG KWAK

REV: ID1:

06/27/05

ID2:

104553 0030569

STATUS: PHONE:

713/690-3044

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS:

PRP: PRP ADDRESS:

PRP CONTACT: PRP PHONE:

8/31/1992

10/21/1992 minor soil contamination - does not require a rap

Final concurrence issued, case close

KWAK SUNG

2923 FONTANA HOUSTON TX 77043 SUNG KWAK 713/690-3044

Removed From Ground

08011992

01011978

01011944

No Variance

Not Reported

0003000 Gallons

LUST INFORMATION

TANK NUMBER:

STATUS:

STATUS DATE: INSTALL DATE:

REGISTERED DATE: CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

Steel CORROSION PROTECTION: - None

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

Not Reported

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

SUBSTANCE STORED:

PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

Steel

- None No Variance

GASOLINE

- - - None No Variance - - - None

No Variance

No Variance

- Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS SEARCH ID: 3 DIST/DIR: 0.48 SE MAP ID: 5 NAME: FAST STOP 46 06/27/05 REV: ADDRESS: 10621 EASTEX FRWY ID1: 104553 HOUSTON TX 77093 0030569 ID2: HARRIS STATUS: CONTACT: SUNG KWAK PHONE: 713/690-3044 TANK NUMBER: STATUS: Removed From Ground STATUS DATE: 08011992 INSTALL DATE: 01011978 REGISTERED DATE: 01011944 CAPACITY: 0002500 Gallons EXT CONTAINMENT DESIGN: CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION: - None CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 2 EQUIP INSTALL DATE: INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER: TYPE OF PIPE: PIPE MATERIAL: Steel PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION: - None PIPE CORROSION PROT VARIANCE: No Variance SUBSTANCE STORED: GASOLINE TANK RLSE DETECTION METHODS: - - - None No Variance TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: - - - None

TANK NUMBER:

STATUS: Removed From Ground

STATUS DATE: 08011992 INSTALL DATE: 01011978 REGISTERED DATE: 01011944 CAPACITY: 0002500 Gallons EXT CONTAINMENT DESIGN:

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION: - Continued on next page -- None

No Variance

No Variance

3

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

LEAKING UNDERGROUND STORAGE TANKS					
SEARCH ID: 3	DIST/DIR: 0.48 SE		MAP ID:		
NAME: FAST STOP 46 ADDRESS: 10621 EASTEX FRWY HOUSTON TX 77093 HARRIS CONTACT: SUNG KWAK		REV: ID1: ID2: STATUS: PHONE:	06/27/05 104553 0030569 713/690-3044		
CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS: STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS: STG 2 EQUIP INSTALL DATE:	No Variance Not Reported Not Reported				
INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER:					
TYPE OF PIPE: PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION: PIPE CORROSION PROT VARIANCE:	Steel None No Variance				
SUBSTANCE STORED: TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:	GASOLINE None No Variance None No Variance No Variance				

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

LEAKING	UNDERGROUND	STORAGE TANK	S
---------	-------------	--------------	---

SEARCH ID: 6

DIST/DIR:

0.50 SE

MAP ID:

NAME:

SAUNDERS ROAD TEXACO

ADDRESS: 10500A EASTEX FWY

**HOUSTON TX 77093** 

HARRIS CONTACT: JIM HOYAK REV:

06/27/05

ID1: ID2:

103841 0030575

STATUS: PHONE:

713/676-0400

SITE INFORMATION

REPORTED:

ENTERED INTO SYSTEM:

SITE PRIORITY:

SITE STATUS:

PRP:

PRP ADDRESS:

PRP CONTACT: PRP PHONE:

6/25/1992

8/9/1992

no gw impacted, no apparent threats or impacts to receptors

Final concurrence issued, case close MARSH PETROLEUM CORP

PO BOX 30068

HOUSTON TX 77249

JIM HOYAK 713/676-0400

LUST INFORMATION

TANK NUMBER:

STATUS:

STATUS DATE:

INSTALL DATE:

REGISTERED DATE:

CAPACITY:

EXT CONTAINMENT DESIGN:

CONSTRUCTION MATERIAL:

CORROSION PROTECTION:

CORROSION PROT VARIANCE: STG 1 VAPOR RECOVERY EQUIP STATUS:

STG 1 EQUIP INSTALL DATE:

STG 2 VAPOR RECOVERY EQUIP STATUS:

STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:

INSTALLER NAME:

INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL:

PIPE DESIGN EXT CONTAINMENT:

PIPE CONECTORS & VALVES:

PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED: TANK RLSE DETECTION METHODS:

TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS:

PIPE RLSE VARIANCE:

SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE:

In Use

01011983 05081986

0010000 Gallons

Steel

- None

No Variance

Not Reported

Not Reported

- None

No Variance

GASOLINE - - - None

No Variance - - - None

No Variance

No Variance

- Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

JOB:

31196

LEAKING UNDERGROUND STORAGE TANKS SEARCH ID: 6 DIST/DIR: 0.50 SE MAP ID: NAME: SAUNDERS ROAD TEXACO REV: 06/27/05 ADDRESS: 10500A EASTEX FWY ID1: 103841 **HOUSTON TX 77093** ID2: 0030575 STATUS: HARRIS CONTACT: JIM HOYAK 713/676-0400 PHONE: TANK NUMBER: STATUS: In Use STATUS DATE: INSTALL DATE: 01011983 REGISTERED DATE: 05081986 CAPACITY: 0010000 Gallons EXT CONTAINMENT DESIGN: CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION: - None CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 2 EQUIP INSTALL DATE: INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER: TYPE OF PIPE: PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION: - None PIPE CORROSION PROT VARIANCE: No Variance SUBSTANCE STORED: GASOLINE TANK RLSE DETECTION METHODS: - - - None No Variance TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: - - - None PIPE RLSE VARIANCE: No Variance SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE: No Variance TANK NUMBER: 2 STATUS: In Use STATUS DATE: INSTALL DATE: 01011983 05081986 REGISTERED DATE: CAPACITY: 0010000 Gallons EXT CONTAINMENT DESIGN: CONSTRUCTION MATERIAL: Steel CORROSION PROTECTION: - Continued on next page -

- None

TARGET SITE:

2900 BRIARWICK LANE

JOB:

31196

**HOUSTON TX 77093** LEAKING UNDERGROUND STORAGE TANKS SEARCH ID: 6 0.50 SE DIST/DIR: MAP ID: 4 NAME: SAUNDERS ROAD TEXACO 06/27/05 REV: ADDRESS: 10500A EASTEX FWY ID1: 103841 HOUSTON TX 77093 ID2: 0030575 HARRIS STATUS: CONTACT: JIM HOYAK PHONE: 713/676-0400 CORROSION PROT VARIANCE: No Variance STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 1 EQUIP INSTALL DATE: STG 2 VAPOR RECOVERY EQUIP STATUS: Not Reported STG 2 EQUIP INSTALL DATE: INSTALLER COMPANY:

INSTALLER COMPANY: INSTALLER NAME: INSTALLER LICENSE NUMBER:

TYPE OF PIPE:

PIPE MATERIAL: PIPE DESIGN EXT CONTAINMENT: PIPE CONECTORS & VALVES: PIPE CORROSION PROTECTION:

PIPE CORROSION PROT VARIANCE:

SUBSTANCE STORED: TANK RLSE DETECTION METHODS: TANK RLSE DETECTION VARIANCE: PIPE RLSE DETECTION METHODS: PIPE RLSE VARIANCE: SPILL/OVERFILL PREVENTION: SPILL/OVERFILL VARIANCE: No Variance

- None

GASOLINE
- - - None
No Variance
- - - None
No Variance
- No Variance

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

OTHER SITE

SEARCH ID: 2

DIST/DIR:

0.16 NW

MAP ID:

2

ALL AROUND VACUME SERVICE

ADDRESS:

10759 ROYAL PINE DRIVE

HOUSTON TX 77093

HARRIS

CONTACT: STAN PORTER

REV:

06/27/2005

ID1: ID2:

IHW-49111

NOT REPORTED

STATUS: PHONE:

INACTIVE 713-697-3696

FACILITY INFORMATION:

REGISTRATION NUMBER:

INITIAL NOTIFICATION DATE:

LAST AMMENDMENT DATE:

EPA ID:

TCEQ PERMIT:

SITE PRIMARY STD. IND. CODE:

GENERATOR OF WASTE:

RECEIVERS OF WASTE:

TRANSPORTERS OF WASTE:

TRANSFER FACILITY:

MEXICAN FACILITY (Maquiladora):

TYPE OF GENERATOR:

INDUSTRIAL WASTE PERMIT NUMBER: MUNICIPAL WASTE PERMIT NUMBER:

MAILING ADDRESS:

MAILING ADDRESS 2:

MAILING ADDRESS 3: MAILING COUNTRY:

49111

19850214

20031211

Not reported

Not reported

42120 - Trans. & Utilities - Local Trucking, Without Storage

Yes

No

Not reported/Not reported

Not reported

Not reported

PO Box 11386 Houston TX 77293 -

LOCATION DESCRIPTION: 10759 Royal Pine Drive, Houston, TX

OWNER INFORMATION

COMPANY or INDIVIDUAL S NAME:

CONTACT:

CONTACT PHONE:

OWNER MAILING ADDRESS:

OWNER MAILING ADDRESS 2:

OWNER P. O. BOX: OWNER TELEPHONE:

OWNER FAX: OWNER EMAIL: TYPE OF BUSINESS: All Around Vacume Service

Stan Porter 713-697-3696

Houston TX 77293-

PO Box 11386

713-697-3696 Not reported

Not reported Unknown

TARGET SITE:

2900 BRIARWICK LANE **HOUSTON TX 77093** 

JOB:

31196

DODA	COD	CIT	CE
RCRA	CUR	OLI	E

SEARCH ID: 1

DIST/DIR:

0.80 NE

MAP ID:

1

NAME:

PORTAWASH SYSTEMS INC

ADDRESS: 3425 MOHAWK ST

HOUSTON TX 77093

CONTACT: ENVIRONMENTAL MANAGER

HARRIS

REV: ID1:

12/10/05

TXD982561375

ID2:

STATUS: CA

PHONE: 281-590-5211

SITE INFORMATION

CONTACT INFORMATION:

ENVIRONMENTAL MANAGER

RAVENSWORTH DR HOUSTON TX 77031

PHONE:

CONTACT INFORMATION:

DAVID BAEDER

PO BOX 111115

HOUSTON TX 772931115

PHONE:

2815905211

N-NO

N-NO

N-NO

N-NO

N-NO

N-NO

UNIVERSE INFORMATION:

BOYSNC:

GPRA PERMIT: GPRA POSTCLOSURE:

GPRA CA:

GPRA CME:

PERM PROG:

PREM WRKLD: CLOSURE WRKLD:

P C WRKLD:

SUBJCA: SUBJCA TSD 3004:

SUBJCA NON TSD: CA WRKLD:

Y - NON TSDFS WHERE CORRECTIVE ACTION HAS BEEN IMPOSED

N-NO

N-NO

N-NO N

GEN STATUS:

NAIC INFORMATION

42272 - PETROLEUM AND PETROLEUM PRODUCTS WHOLESALERS (EXCEPT BULK STATIONS AND TERMINALS)

92411 - ADMINISTRATION OF AIR AND WATER RESOURCE AND SOLID WASTE MANAGEMENT PROGRAMS

811111 - GENERAL AUTOMOTIVE REPAIR

561439 - OTHER BUSINESS SERVICE CENTERS (INCLUDING COPY SHOPS)

561499 - ALL OTHER BUSINESS SUPPORT SERVICES

RAATS INFORMATION:

DOCKET NUMBER: DATE RECEIVED:

RCRA-VI-107-H

INITIAL DATE: 3291991 - Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

	R	CRA COR SITE			
SEARCH ID: 1	DIS	T/DIR: 0.80	NE	MAP ID:	1
NAME: PORTAWASH SYS ADDRESS: 3425 MOHAWK ST HOUSTON TX 770' HARRIS CONTACT: ENVIRONMENTAL	93		REV: ID1: ID2: STATUS: PHONE:	12/10/05 TXD982561375 CA 281-590-5211	
ORDER TYPE:	3008(A)		THOILE.	201:070:0211	
ENFORCEMENT INFORMATIO	DN:				
AGENCY: TYPE:	S - STATE 120 - WRITTEN INFO		2/18	/1993	
AGENCY: TYPE:	E - EPA 120 - WRITTEN INFO	DATE: RMAL	2/28	/1990	
AGENCY:	S - STATE	DATE:	5/21	/1997	
TYPE:	110 - VERBAL INFOR		er/ 44 A		
AGENCY: TYPE:	E - EPA 310 - FINAL 3008(A)	DATE: COMPLIANCE ORDE		/1992	
AGENCY: TYPE:	E - EPA 310 - FINAL 3008(A)	DATE: COMPLIANCE ORDE		/1991	
AGENCY: TYPE:	S - STATE 110 - VERBAL INFOR	DATE:	6/1/	1995	
AGENCY: TYPE:	S - STATE 120 - WRITTEN INFO	DATE: RMAL	6/27	//1997	
VIOLATION INFORMATION:					
VIOLATION NUMBER:	0001	RESPONSIBLE:	E - 1	EPA	
DETERMINED: CITATION: RESOLVED:	3/10/1989 335.10B 2/11/1992	DETERMINED BY:	S - 5	STATE	
TYPE:	GMR - GENERATOR	MANIFEST REQUIRE	EMENTS		
VIOLATION NUMBER: DETERMINED: CITATION:		RESPONSIBLE: DETERMINED BY:	E - 1 S - 5	EPA STATE	
RESOLVED: TYPE:	2/11/1992 GOR - GENERATOR	OTHER REQUIREME	NTS		
VIOLATION NUMBER: DETERMINED: CITATION:		RESPONSIBLE: DETERMINED BY:		EPA STATE	
RESOLVED: TYPE:	2/1/1993 GLB - GENERATOR I	LAND BAN REQUIRE	EMENTS		
VIOLATION NUMBER: DETERMINED:		RESPONSIBLE: DETERMINED BY:		EPA STATE	
CITATION: RESOLVED:	2/11/1992		- Co	ntinued on next page -	

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

RCRA COR SITE						
SEARCH I	<b>D</b> : 1	П	DIST/DIR:	0.80 1	NE	MAP ID: 1
ADDRESS:	PORTAWASH SYST 3425 MOHAWK ST HOUSTON TX 7709: HARRIS ENVIRONMENTAL	3			REV: ID1: ID2: STATUS: PHONE:	12/10/05 TXD982561375 CA 281-590-5211
ГҮРЕ:		SWR				
VIOL LETON N	HIMPED	0005	PROPONICHI			
VIOLATION N DETERMINEI CITATION:		0005 9/15/1989	RESPONSII DETERMIN			EPA EPA
RESOLVED:		2/11/1992				
TYPE:		GLB - GENERATO	R LAND BAN	REQUIRE	MENTS	
VIOLATION S	HIMDED.	0005	DECRONOR	N. F.		CTATE
VIOLATION N		0005	RESPONSII			STATE
DETERMINE	);	11/2/1992	DETERMIN	ED BY:	S -	STATE
CITATION:		335.6c 2/1/1993				
RESOLVED: TYPE:		2/1/1993 SWR				
. 1110.		JWK				
VIOLATION N		0006	RESPONSI	BLE:	Ε-	EPA
DETERMINE	D;	9/15/1989	DETERMIN	ED BY:	E-	EPA
CITATION:						
RESOLVED:		2/11/1992				
TYPE:		GLB - GENERATO	R LAND BAN	REQUIRE	MENTS	
VIOLATION N	NUMBER:	0006	RESPONSI	BLE:	S-	STATE
DETERMINE		11/2/1992	DETERMIN			STATE
CITATION:		268.7a 7		The second second		
RESOLVED:		7/15/1993				
TYPE:		GLB - GENERATO	R LAND BAN	REQUIRE	MENTS	
VIOLATION N	HIMDED.	0007	DESDONSH	DI E.	c	PTATE
DETERMINE		11/2/1992	RESPONSII			STATE
CITATION:	<i>y</i> :		DETERMIN	ED BY:	5 -	SIAIE
RESOLVED:		335.114b 7/15/1993				
TYPE:		7/15/1993 SWR				
		J.11.1				
VIOLATION N	NUMBER:	0008	RESPONSII	BLE:	S -	STATE
DETERMINEI	D:	11/2/1992	DETERMIN	ED BY:	S -	STATE
CITATION:		335.71a				
RESOLVED:		7/15/1993				
TYPE:		SWR				
VIOLATION N	NUMBER:	0009	RESPONSII	BLE:	S -	STATE
DETERMINE		11/2/1992	DETERMIN			STATE
CITATION:		335.69a4/262.35				
RESOLVED:		7/15/1993				
TYPE:		GOR - GENERATO	OR OTHER REC	UIREME	NTS	
VIOLATION N	NIMRED.	0010	RESPONSI	DI E.	c	STATE
DETERMINE		11/2/1992	DETERMIN			STATE STATE
CITATION:		335.2a/270.1c	DETERMIN	ED DI:	5 -	SIMIE
RESOLVED:		7/15/1993				
TYPE:		DOR - TSD OTHER	REQUIREME	NTS		
		DON-13D OTHER	LALQUIREME			Continued on next need
	NUMBER:	0011	RESPONSI		- C	Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

RCRA COR SITE						
SEARCH ID: 1	DIS	ST/DIR:	0.80 N	Е	MAP ID:	1
NAME: PORTAWASH SYST ADDRESS: 3425 MOHAWK ST				REV: ID1:	12/10/05 TXD982561375	
HOUSTON TX 7709				ID2:	1710702001370	
HARRIS				STATUS:		
CONTACT: ENVIRONMENTAL	MANAGER			PHONE:	281-590-5211	
DETERMINED:	11/2/1992	DETERMINED	BY:	S -	STATE	
CITATION:	265.192a/335.112a9					
RESOLVED:	7/15/1993					
TYPE:	DOR - TSD OTHER F	REQUIREMENTS	5			
VIOLATION NUMBER:	0012	RESPONSIBLI	ē:	S -	STATE	
DETERMINED:		DETERMINED			STATE	
CITATION:	265.192b/335.112a9			#2%		
RESOLVED:	7/15/1993					
TYPE:	DOR - TSD OTHER F	REQUIREMENTS	S			
VIOLATION NUMBER:	0013	RESPONSIBLE	E:	S -	STATE	
DETERMINED:	11/2/1992				STATE	
CITATION:	265.193a1/335.112a9	Dataman			311112	
RESOLVED:	7/15/1993					
TYPE:	DOR - TSD OTHER F	REQUIREMENTS	5			
VIOLATION NUMBER:	0014	RESPONSIBLE	2.	S -	STATE	
DETERMINED:		DETERMINED			STATE	
CITATION:	265.193b/335.112a9	DETERMINE			31.11.2	
RESOLVED:	7/15/1993					
TYPE:	DOR - TSD OTHER F	REQUIREMENTS	S			
VIOLATION NUMBER:	0015	RESPONSIBLI	F.+	S -	STATE	
DETERMINED:		DETERMINED			STATE	
CITATION:	265.195c/335.112a9					
RESOLVED:	2/1/1993					
TYPE:	DOR - TSD OTHER F	REQUIREMENTS	S			
VIOLATION NUMBER:	0016	RESPONSIBLI	E:	S-	STATE	
DETERMINED:	11/2/1992					
CITATION:	265.197c/335.112a9					
RESOLVED:	2/1/1993					
TYPE:	DCL - TSD CLOSUR	E/POST CLOSUI	RE REQ	UIREMENTS		
VIOLATION NUMBER:	0017	RESPONSIBLI	E:	S-	STATE	
DETERMINED:	11/2/1992	DETERMINED			STATE	
CITATION:	265.140a/335.112a7					
RESOLVED:	2/1/1993					
TYPE:	DFR - TSD FINANCI	AL RESPONSIB	ILITY R	EQUIREMEN	ITS	
VIOLATION NUMBER:	0018	RESPONSIBLI	E:	S-	STATE	
DETERMINED:	11/2/1992	DETERMINED BY:		S - STATE		
CITATION:	265.173/335.112 8					
RESOLVED:	2/1/1993					
TYPE:	DOR - TSD OTHER F	REQUIREMENT	S			
VIOLATION NUMBER:	0019	RESPONSIBLI	E:	S-	STATE	
DETERMINED:	ř1/2/1992	DETERMINEI			STATE	
CITATION:	265.174/335.112 8			- C	ontinued on next page	_
RESOLVED:	2/1/1993					

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

		RCRA COI	RSITE		
SEARCH ID: 1		DIST/DIR:	0.80 NE	MAP ID:	1
NAME: PORTAWA	ASH SYSTEMS INC		REV:	12/10/05	
ADDRESS: 3425 MOH			ID1:	TXD982561375	
HOUSTON	TX 77093		ID2:		
HARRIS			STATU		
CONTACT: ENVIRON	MENTAL MANAGER		PHONE	281-590-5211	
TYPE:	DOR - TSD OT	HER REQUIREMEN	NTS		
VIOLATION NUMBER:	0020	RESPONSIE	BLE:	S - STATE	
DETERMINED:	11/2/1992	DETERMIN	ED BY:	S - STATE	
CITATION:	268.50 2 1				
RESOLVED:	2/1/1993				
ГҮРЕ:	DLB - TSD LA	ND BAN REQUIRE	MENTS		
VIOLATION NUMBER:	0021	RESPONSI	BLE:	S - STATE	
DETERMINED:	11/10/1993	DETERMIN		S - STATE	
CITATION:	335.15(2)				
RESOLVED:	12/14/1994				
ГҮРЕ:	SWR				
VIOLATION NUMBER:	0022	RESPONSI	BLE:	S - STATE	
DETERMINED:	11/3/1993	DETERMIN		S - STATE	
CITATION:	335.2a 335.43				
RESOLVED:	9/7/1994				
ГҮРЕ:	SWR				
VIOLATION NUMBER:	0023	RESPONSI	BLE:	S - STATE	
DETERMINED:	11/3/1993	DETERMIN		S - STATE	
CITATION:	335.2b				
RESOLVED:	9/7/1994				
ГҮРЕ:	SWR				
VIOLATION NUMBER:	0024	RESPONSI	BLE:	S - STATE	
DETERMINED:	6/1/1995	DETERMIN		S - STATE	
CITATION:	335.69b/262.34	b			
RESOLVED:	6/5/1995				
ГҮРЕ:	GOR - GENER	ATOR OTHER REQ	UIREMENTS		
VIOLATION NUMBER:	0025	RESPONSI	BLE:	S - STATE	
DETERMINED:	6/1/1995	DETERMIN	ED BY:	S - STATE	
CITATION:	335.112a2/69a4	/265.35			
RESOLVED:	6/5/1995				
ГҮРЕ:	GOR - GENER	ATOR OTHER REQ	UIREMENTS		
VIOLATION NUMBER:	0026	RESPONSI	BLE:	S - STATE	
DETERMINED:	6/1/1995	DETERMIN	ED BY:	S - STATE	
CITATION:	335.112a8/69a1	/265.173a			
RESOLVED:	6/1/1995				
ГҮРЕ:	GOR - GENER	ATOR OTHER REQ	UIREMENTS		
VIOLATION NUMBER:	0027	RESPONSI	BLE:	S - STATE	
DETERMINED:	5/21/1997	DETERMIN	ED BY:	S - STATE	
CITATION:	335.69a2-3/262				
RESOLVED:	5/21/1997				
	COP CENED	ATOR OTHER REQ	LUDEMENTS		
TYPE:	GOR - GENER	ATOK OTHER REQ	UIKEMENIS	- Continued on next page -	

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

		RCRA COR SIT	ΓE	
SEARCH ID: 1	D	DIST/DIR: 0.8	30 NE	MAP ID: 1
NAME: PORTAWASH SYST ADDRESS: 3425 MOHAWK ST HOUSTON TX 7709 HARRIS CONTACT: ENVIRONMENTAL	3		REV: ID1: ID2: STATUS: PHONE:	12/10/05 TXD982561375 CA 281-590-5211
DETERMINED: CITATION: RESOLVED: IYPE:	335.69a4/265.35 5/21/1997	DETERMINED B		- STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: FYPE:	0029 5/21/1997 335.69a1A/265.174 5/28/1997 GOR - GENERATO	RESPONSIBLE: DETERMINED B	Y: S	- STATE - STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0030 5/21/1997 335.13cd 5/28/1997 SWR	RESPONSIBLE: DETERMINED B		- STATE - STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0031 5/21/1997 335.62/262.11 1/28/1998 GOR - GENERATO	RESPONSIBLE: DETERMINED B	Y: S	- STATE - STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0032 5/21/1997 335.6c 8/19/1997 SWR	RESPONSIBLE: DETERMINED B		- STATE - STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0033 5/21/1997 335.6h 8/19/1997 SWR	RESPONSIBLE: DETERMINED B		- STATE - STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0034 5/21/1997 335.9a 8/19/1997 SWR	RESPONSIBLE: DETERMINED B		- STATE - STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0035 5/21/1997 335.9a2 8/19/1997 SWR	RESPONSIBLE: DETERMINED B		- STATE - STATE
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED:	0036 5/21/1997 335.15(2-3) 8/19/1997	RESPONSIBLE: DETERMINED B	Y: S	- STATE - STATE Continued on next page -

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

		RCRA COR SITE			
SEARCH ID: 1	I	DIST/DIR: 0.80 N	NE	MAP ID:	
NAME: PORTAWASH SYSTE ADDRESS: 3425 MOHAWK ST HOUSTON TX 77093 HARRIS CONTACT: ENVIRONMENTAL M			REV: 12/10/05 ID1: TXD982: ID2: STATUS: CA PHONE: 281-590-	561375	
ГҮРЕ:	SWR				
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0037 5/21/1997 335.10b18/APPEN 8/19/1997 GMR - GENERATO		S - STATE S - STATE		
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0038 5/21/1997 335.10b22 8/19/1997 SMR	RESPONSIBLE: DETERMINED BY:	S - STATE S - STATE		
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0039 5/21/1997 335.10d3/262.23a3 8/19/1997 GMR - GENERATO	RESPONSIBLE: DETERMINED BY: OR MANIFEST REQUIRE	S - STATE S - STATE MENTS		
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0040 5/21/1997 335.431c/268.7a1(7 8/19/1997 GLB - GENERATO	RESPONSIBLE: DETERMINED BY: 7) OR LAND BAN REQUIRE	S - STATE S - STATE MENTS		
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0041 5/21/1997 335.12a2 8/19/1997 SWR	RESPONSIBLE: DETERMINED BY:	S - STATE S - STATE		
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0042 5/21/1997 335.69a4/265.37a1( 8/19/1997	RESPONSIBLE: DETERMINED BY: (3)(4) OR OTHER REQUIREMENT	S - STATE S - STATE		
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED: TYPE:	0043 5/21/1997 335.69a4/265.53b 8/19/1997	RESPONSIBLE: DETERMINED BY: OR OTHER REQUIREMEN	S - STATE S - STATE		
VIOLATION NUMBER: DETERMINED: CITATION: RESOLVED:	0044 5/21/1997 335.69a4/265.16d1 8/19/1997	RESPONSIBLE: DETERMINED BY:	S - STATE S - STATE		
TYPE: VIOLATION NUMBER:	0045	GOR - GENERATOR OTHER REQUIREMENTS  0045 RESPONSIBLE:		- Continued on next page -	

TARGET SITE:

2900 BRIARWICK LANE HOUSTON TX 77093

JOB:

31196

RCRA COR SITE

SEARCH ID: 1

DIST/DIR:

0.80 NE

MAP ID:

NAME:

PORTAWASH SYSTEMS INC

ADDRESS:

3425 MOHAWK ST HOUSTON TX 77093

HARRIS

CONTACT: ENVIRONMENTAL MANAGER

REV: ID1:

12/10/05

TXD982561375

ID2:

STATUS:

PHONE:

281-590-5211

DETERMINED:

CITATION:

5/21/1997

335.69a1B/265.192abdg

RESOLVED: TYPE:

0046

GOR - GENERATOR OTHER REQUIREMENTS

VIOLATION NUMBER:

DETERMINED:

RESPONSIBLE:

S - STATE

CITATION:

DETERMINED BY:

DETERMINED BY:

S - STATE

S - STATE

RESOLVED:

335.69a1B/265.193e2i

TYPE:

GOR - GENERATOR OTHER REQUIREMENTS

GOR - GENERATOR OTHER REQUIREMENTS

GOR - GENERATOR OTHER REQUIREMENTS

5/21/1997

RESPONSIBLE:

S - STATE

DETERMINED: CITATION:

5/21/1997 335.69a1B/265.195a1(2)(4)c

0048

RESOLVED: TYPE:

DETERMINED BY:

S - STATE

S - STATE

S - STATE

8/19/1997

5/21/1997

1/28/1998

335.8d/265.197ab

VIOLATION NUMBER:

VIOLATION NUMBER:

DETERMINED:

CITATION:

RESOLVED:

TYPE:

VIOLATION NUMBER:

DETERMINED:

CITATION: RESOLVED: 0049

RESPONSIBLE:

DETERMINED BY:

RESPONSIBLE:

DETERMINED BY:

S - STATE

S - STATE

5/21/1997 335.431c/268.7a

8/19/1997

TYPE:

GLB - GENERATOR LAND BAN REQUIREMENTS

CORRECTIVE ACTION INFORMATION

CA EVENT:

CA075ME - CA PRIORITIZATION-MEDIUM CA PRIORITY

HAZARDOUS WASTE INFORMATION:

Cresol

Trichloroethylene

The following spent non-halogenated solvents: Xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/ blends containing, b

The following spent non-halogenated solvents: toluene, methyl ethyl ketone, carbon disulfide, isobutanol, pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a to

The following spent non-halogenated solvents: cresols, cresylic acid, and nitrobenzene; all spent solvent mixtures/blends containing, before use, a total of ten percent or more (by volume) of one or more of the above non-hal

The following spent halogenated solvents: Tetrachloroethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2-trifluoroethane, ortho-dichlorobenzene, trichlorofluoromethane

The following spent halogenated solvents used in degreasing: Tetrachloroethylene, trichlorethylene, methylene chloride, 1,1,1-trichloroethane, carbon tetrachloride and chlorinated fluorocarbons; all spent solvent mixtures/bl

Ignitable waste

Corrosive waste

Tetrachloroethylene

#### **Environmental FirstSearch Database Descriptions**

NPL: EPA NATIONAL PRIORITY LIST - Database of confirmed, proposed or deleted Superfund sites.

**CERCLIS:** *EPA* COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION AND LIABILITY INFORMATION SYSTEM - Database of current and potential Superfund sites currently or previously under investigation.

**NFRAP:** *EPA* COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION AND LIABILITY INFORMATION SYSTEM ARCHIVED SITES - database of Archive designated CERCLA sites that, to the best of EPA's knowledge, assessment has been completed and has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

**RCRA TSD:** *EPA* RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM TREATMENT, STORAGE, and DISPOSAL FACILITIES. - Database of facilities licensed to store, treat and dispose of hazardous waste materials.

**RCRA COR:** *EPA* RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM SITES - Database of RCRA facilities with reported violations and subject to corrective actions.

RCRA GEN: EPA RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM SITES - Database of facilities that generate or transport hazardous waste or meet other RCRA requirements.LGN - Large Quantity GeneratorsSGN - Small Quantity GeneratorsVGN - Conditionally Exempt Generator.Included are RAATS (RCRA Administrative Action Tracking System) and CMEL (Compliance Monitoring & Enforcement List) facilities.

**ERNS:** *EPA/NRC* EMERGENCY RESPONSE NOTIFICATION SYSTEM - Database of emergency response actions. Data since January 2001 has been received from the National Response System database as the EPA no longer maintains this data.

**STATE SITES:** *TCEQ* Listing of sites contained in the State Superfund Registry, listing of all sites in the Voluntary Cleanup Program (VCP) and the Innocent Owner/Operator Program (IOP). Some VCP and IOP sites are noted as having institutional controls placed on them.

SWL: TCEQ Listing of all permitted solid waste landfills, transfer stations, and incinerators

**OTHER:** *TCEQ* Texas Industrial Hazardous Waste Notice of Registration (IHW NOR) data. The TCEQ enters all information submitted by industrial and hazardous waste transporters, receivers (including recyclers), generators and one time shipments into a database that tracks industrial and hazardous waste generation and management activities in the state of Texas. All facilities of these types receive a solid waste registration number.

REG UST/AST: TCEQ Listing of all underground petroleum storage tanks

LEAKING UST: TCEQ Listing of all leaking underground petroleum storage tanks

**OTHER:** *EPA* SECTION SEVEN TRACKING SYSTEM (SSTS) – database of registration and production data for facilities which manufacture pesticides. AEROMETRIC INFORMATION RETRIEVAL SYSTEM (AIRS) – database of detailed information pertaining to sites which submit air emissions reports. Developed under the Clean Air Act, this database also maintains data on compliance status and enforcement actions.

**RADON:** NTIS NATIONAL RADON DATABASE - EPA radon data from 1990-1991 national radon project collected for a variety of zip codes across the United States.

#### **Environmental FirstSearch Database Sources**

NPL: EPA Environmental Protection Agency

Updated quarterly

CERCLIS: EPA Environmental Protection Agency

Updated quarterly

NFRAP: EPA Environmental Protection Agency.

Updated quarterly

RCRA TSD: EPA Environmental Protection Agency.

Updated quarterly

RCRA COR: EPA Environmental Protection Agency.

Updated quarterly

RCRA GEN: EPA Environmental Protection Agency.

Updated quarterly

ERNS: EPA/NRC Environmental Protection Agency

Updated semi-annually

**STATE SITES:** *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Remediation Division

Updated quarterly

SWL: TCEQ The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Municipal Solid Waste Permits Section

Updated annually

OTHER: TCEQ The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration

Updated quarterly

**REG UST/AST:** *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Petroleum Storage Tank Program

#### Updated quarterly

**LEAKING UST:** *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Petroleum Storage Tank Program

Updated quarterly

OTHER: EPA Environmental Protection Agency

Updated quarterly

RADON: NTIS Environmental Protection Agency, National Technical Information Services

Updated periodically

# Environmental FirstSearch Street Name Report for Streets within 1 Mile(s) of Target Property

**TARGET SITE:** 2900 BRIARWICK LANE HOUSTON TX 77093

Street Name	Dist/Dir	Street Name	Dist/Dir
Aldine Westfield Rd	0.59 SW	Little York Rd	0.24 N-
Allbritton Dr	0.32 SW	Littlecrest Rd	0.69 NE
Amalie St	0.96 SE	Lone Oak Rd	0.44 NW
Bantum St	0.31 SW	Lowrie St	0.61 SE
Barksdale Dr	0.28 NE	Macha	0.78 SE «
Bentley St	0.28 NE	Margaret Dr	0.24 SW
Briarwick Ln	0.01 NE	Marilyn Ln	0.14 SE
Burden St	0.77 SW	Marzelle St	0.27 SE
Carlington Dr	0.27 SW	Mohawk Ln	0.77 NE
Cedar Hill Ln	0.59 NE	Mooney Rd	0.94 NE
Chamberlain Rd	0.69 NW	Moreau St	0.37 SW
Chapis St	0.74 SW	Nuggent St	0.49 NE
Charles St	0.37 SW	Orlando St	0.21 SE
Charter Oaks Dr	0.42 NE	Park Ln	0.43 -W
Cohutta Ln	0.79 NE	Parker Rd	0.56 SE
Copley Ln	0.89 NE	Pine Tree Dr	0.21 NW
Cresline St	0.56 SW	Priest Dr	1.00 SW
Cricket Ln	0.37 N-	Raymondville Rd	0.42 SW
Cromwell Rd	0.71 NE	Rosemary Ln	0.65 NE
Darwin Rd	0.87 NE	Rothermel Rd	0.06 N-
Deutser St	0.40 SW	Royal Pine Dr	0.01 -W
Dodson Rd	0.56 SE	Sagebrush Dr	0.44 NW
Downs Ln	0.98 SE	Saunders Rd	0.45 SE
Durwood St	0.12 NE	Schilder Dr	0.86 SW
Eastex Frwy Serv Dr	0.45 SE	Seven Mile Ln	0.53 NW
Eastex Frwy Service	0.64 SE	Shady Ln	0.16 NW
Eastex Fwy	0.47 SE	Skinner Rd	0.61 SW
Edgeworth St	0.68 SW	Somerset Ln	0.32 NW
Epsom Dr	0.69 SE	Stafford Dr	0.44 NE
Exeter St	0.97 SW	Strickland Dr	0.35 -E
Fleetwood Dr	0.17 NE	Symbol Rd	1.00 NE
Folger St	0.74 S-	Terrell	0.97 SE
Foy Ln	0.10 NE	Three Sisters St	0.47 NE
Friendly Rd	0.68 SE	Tolar Ave	0.85 NE
Gager St	0.69 SE	Topping St	0.68 SE
Gateway Dr	0.27 SW	Trenton Rd	0.32 NW
Goodloe St	0.41 SW	Trippel St	0.73 SW
Gwen St	0.68 SW	Trout St	0.88 S-
Hage St	0.94 SE	Vivian Rd	0.40 NE
Hardwood Ln	0.12 NW	Wages St	0.40 NE 0.75 SE
Haywood St	0.91 SE	Wardmont St	0.89 N-
Hitchcock St	0.81 SE	Wardville St	1.00 NE
Holbrook St	0.98 NE	Warren St	0.40 NE
Hollis St	0.74 SW	Warwick Rd	0.40 NE 0.81 NW
Hopper Rd	0.74 SW 0.82 N-	Wellington St	0.81 NW 0.88 SW
Innsbury Dr	0.98 NW	Wiley Rd	0.55 SE
Jensen Dr	0.45 SE	William Tell St	0.62 NW
Kandarain St			
Nandalalii St	0.77 SW	Willie St	0.89 NE

## Environmental FirstSearch Street Name Report for Streets within 1 Mile(s) of Target Property


TARGET SITE:


2900 BRIARWICK LANE HOUSTON TX 77093


Street Name	Dist/Dir	Street Name	Dist/Dir
Kowis St	0.53 N-	Woody Ln	0.23 SW
Lakewood Dr	0.21 SW	Yorkwood St	0.19 NW
Langley Rd	0.09 SE		
Larry St	0.68 SE		
Bridge Bridge Co.			


APPENDIX-D

















APPENDIX-E




Subject site



Southeast view of property



Sites to the south



Sites to the east



Sites to the north



Sites to the west